

2022-23 List of Planned Maintenance Projects across All Districts

DFE	District	School	Work Element	Rationale
2177	1. Cannock Chase	Bridgtown Primary School	External - Drainage	Safe Warm Dry
3040	1. Cannock Chase	Chadsmoor CofE (VC) Junior School	Fire Safety works	Safe Warm Dry
2180	1. Cannock Chase	Five Ways Primary School	Mechanical - Heating	Decarbonisation - Mechanical Works
2386	1. Cannock Chase	Gorsemoor Primary School	Roof Repair/Replace	Decarbonisation - Roofs
3139	1. Cannock Chase	Hob Hill CE/Methodist (VC) Primary School	Roof Repair/Replace	Decarbonisation - Roofs
3139	1. Cannock Chase	Hob Hill CE/Methodist (VC) Primary School	Mechanical - Pipework	Decarbonisation - Mechanical Works
2369	1. Cannock Chase	Jerome Primary School	External - Playground	Healthy Pupil - Playground Resurfacing
3492	1. Cannock Chase	St Lukes CofE Primary School	Roof Repair/Replace	Decarbonisation - Roofs
2184	1. Cannock Chase	West Hill Primary School	Roof Repair/Replace	Decarbonisation - Roofs
2411	2. Lichfield	Chase Terrace Primary School	Mechanical - Pipework	Decarbonisation - Mechanical Works
3076	2. Lichfield	Christ Church CE(VC) Primary School, Lichfield	Internal - Ceiling/Lighting	Safe Warm Dry
2416	2. Lichfield	Holly Grove Primary School	Internal - Ceiling/Lighting	Safe Warm Dry
4087	2. Lichfield	King Edward VI School - Lichfield	Roof Repair/Replace	Decarbonisation - Roofs
2203	2. Lichfield	Millfield Primary School	External - Playground	Healthy Pupil - Playground Resurfacing
2216	2. Lichfield	Thomas Barnes Primary School	External - Steps	Safe Warm Dry
2216	2. Lichfield	Thomas Barnes Primary School	Windows - Repair/Replace	Decarbonisation - Windows
2309	2. Lichfield	Whittington Primary School	External - Playground	Healthy Pupil - Playground Resurfacing
2340	2. Lichfield	Willows Primary School	Windows - Repair/Replace	Safe Warm Dry
2340	2. Lichfield	Willows Primary School	Internal - Flooring	Safe Warm Dry
3137	3. Newcastle	Baldwins Gate CofE(VC) Primary School	Electrical - Throughout	Safe Warm Dry
2218	3. Newcastle	Dove Bank Primary School	Mechanical - Hot water system	Decarbonisation - Mechanical Works
2218	3. Newcastle	Dove Bank Primary School	External - Playground	Healthy Pupil - Playground Resurfacing
2251	3. Newcastle	Hassell Primary School	Internal - Flooring	Safe Warm Dry
2251	3. Newcastle	Hassell Primary School	Mechanical - Pipework	Decarbonisation - Mechanical Works
3026	3. Newcastle	Hugo Meynell CofE (VC) Primary School	Roof Repair/Replace	Decarbonisation - Roofs
3026	3. Newcastle	Hugo Meynell CofE (VC) Primary School	Internal - Ceiling/Lighting	Decarbonisation - Electrical
2226	3. Newcastle	Springhead Primary School	Electrical - Throughout	Safe Warm Dry
3091	3. Newcastle	St Chad's CofE (C) Primary School	Mechanical - Pipework	Safe Warm Dry
3069	3. Newcastle	St John's CofE (C) Primary School	External - Drainage	Safe Warm Dry
3093	3. Newcastle	St Luke's CofE (C) Primary School	Mechanical - Boilers	Decarbonisation - Mechanical Works
3093	3. Newcastle	St Luke's CofE (C) Primary School	Roof Repair/Replace	Safe Warm Dry
3094	3. Newcastle	St Margaret's CofE (VC) Junior School	External - Retaining Wall	Grounds Maintenance
2263	3. Newcastle	Westlands Primary School	Mechanical - Boilers	Decarbonisation - Mechanical Works
4067	4. Staffs Moorlands	Blythe Bridge High School	Windows - Repair/Replace	Safe Warm Dry
3000	4. Staffs Moorlands	Forsbrook CofE Controlled Primary School	External - Carpark/Driveway	Grounds Maintenance
2166	4. Staffs Moorlands	Squirrel Hayes First School	Windows - Repair/Replace	Safe Warm Dry
3035	4. Staffs Moorlands	St Anne's CofE (VC) Primary School	Mechanical - Hot water system	Safe Warm Dry
3027	5. Stafford	Barlaston First School	Fire Safety works	Safe Warm Dry
2406	5. Stafford	Burton Manor Primary	Roof Repair/Replace	Decarbonisation - Roofs
2208	5. Stafford	Fulford Primary School	Roof Repair/Replace	Decarbonisation - Roofs

2022-23 List of Planned Maintenance Projects across All Districts

DFE	District	School	Work Element	Rationale
4181	5. Stafford	King Edward VI High - Stafford	Mechanical - Boilers	Decarbonisation - Mechanical Works
2315	5. Stafford	Springfield First School, Yarnfield	Electrical - Distribution Boards	Safe Warm Dry
3112	5. Stafford	St. Michael's First School	Electrical - Distribution Boards	Safe Warm Dry
5402	5. Stafford	Stafford Manor	Windows - Repair/Replace	Decarbonisation - Windows
2400	5. Stafford	Tillington Manor	Roof Repair/Replace	Decarbonisation - Roofs
4142	5. Stafford	Walton Priory Middle	External - Drainage	Safe Warm Dry
4142	5. Stafford	Walton Priory Middle	Windows - Repair/Replace	Decarbonisation - Windows
4517	6. South Staffs	Bilbrook Middle	Windows - Repair/Replace	Decarbonisation - Windows
2396	6. South Staffs	Blakeley Heath Primary	External - Playground	Healthy Pupil - Playground Resurfacing
4075	6. South Staffs	Codsall Community High School	Windows - Repair/Replace	Decarbonisation - Windows
2372	6. South Staffs	Perton First School	Mechanical - Boilers	Decarbonisation - Mechanical Works
4170	6. South Staffs	Perton Middle	Refurbishment/Remodelling	Safe Warm Dry
4170	6. South Staffs	Perton Middle	Mechanical - Heating Controls	Decarbonisation - Mechanical Works
3116	6. South Staffs	St. John's, Swindon	Roof Repair/Replace	Safe Warm Dry
2397	6. South Staffs	Westfield Primary	Mechanical - Boilers	Decarbonisation - Mechanical Works
1111	7. East Staffs	Burton PRU	Windows - Repair/Replace	Decarbonisation - Windows
2123	7. East Staffs	Christchurch Primary School	External - Playground	Healthy Pupil - Playground Resurfacing
3500	7. East Staffs	Riverview Primary School	Windows - Repair/Replace	Decarbonisation - Windows
3500	7. East Staffs	Riverview Primary School	Roof Repair/Replace	Decarbonisation - Roofs
3084	7. East Staffs	St Peters CE(VC) First School, Marchington	Mechanical - Pipework	Decarbonisation - Mechanical Works
3084	7. East Staffs	St Peters CE(VC) First School, Marchington	External - Carpark/Driveway	Grounds Maintenance
2140	7. East Staffs	Tower View Primary School	Windows - Repair/Replace	Decarbonisation - Windows
2140	7. East Staffs	Tower View Primary School	Roof repair/replace	Decarbonisation - Roofs
2370	8. Tamworth	Amington Heath Primary School and Nursery	External - Playground	Healthy Pupil - Playground Resurfacing
2370	8. Tamworth	Amington Heath Primary School and Nursery	Roof Repair/Replace	Decarbonisation - Roofs
2346	8. Tamworth	Hanbury's Farm Community Primary School	Windows - Repair/Replace	Decarbonisation - Windows
2348	8. Tamworth	Oakhill Primary School	Roof Repair/Replace	Decarbonisation - Roofs
1105	County Wide	Bridge Short Stay School	External - Playground	Healthy Pupil - Playground Resurfacing
1105	County Wide	Bridge Short Stay School	External - Playground	Healthy Pupil - Playground Resurfacing
7000	County Wide	Chasetown Community School	External - Playground	Healthy Pupil - Playground Resurfacing
	County Wide	Various	AMP Surveys	AMP Surveys